

Product Information

HTF-016C ASTM D3107 Woven Fabric Stretch and Recovery Tester

Use: The Stretch and recovery Tester is developed to determine the amount of fabric stretch, fabric growth, and fabric recovery of fabrics woven in whole or in part from stretch yarns after a specified tension and extension.

Standard: ASTM D3107-2007 Test method for Stretch Properties of Fabrics Woven from Stretch Yarns



Parameters:

1. Test station: 6 group
2. Upper clamp: 6
3. Lower clamp: 6
4. Tension weights: 1.8kg(4lb.) 3 pcs; 1.35kg(3lb.) 3 pcs
5. Specimen size: 50×560mm (L×W)
6. Overall dimension: 1000×500×1500mm (L×W×H)
7. Weight: 65Kg